ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0028	NA	1st A main Nanjappa Layout
Segment No.	**Total Length (m)**	
10/S-W0028/S083344	373.13	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	373.13	77.557065	13.067526	77.559922	13.066966	W0107	W0026

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at 1st A main Nanjappa Layout area in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone	2500000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to Roads and Drains at 1st A main Nanjappa Layout area in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone	010-17-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/106/2016-17	19/08/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
19/08/2016	18/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		MADHAVA RAO

Date of Inspection	Remarks
07/12/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	07/12/2016	06/01/2017	COMPLETED
SE	VASU K M	07/12/2016	06/01/2017	COMPLETED
EE	YARAPPA REDDY	07/12/2016	06/01/2017	COMPLETED
AEE	SHIVAKUMAR	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED